

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, September 15, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12807+43 - 12866+36 MVP-RO-283	Weather:	Dry

NUC	illoke Couli	ιy	IAI A L -	110-203							
	<u>ACTI</u>	VE STAGE	OF C	CONSTRUCTION: (C	Check all	that apply)					
	Tree Felling	g	\boxtimes	Clearing/Grubbing	\boxtimes	Grading		Trenching	☐ Stringing/Welding		
	Lowering/Backfilling		☐ Final Restoration			☐ Temp. Stabilization		Perm. Stabilization		Res	source Crossing
									Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						erosion and	\boxtimes			
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes				
	3.	Areas of o	offsite	sediment deposition	observe	d?				\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-IJ89, S-IJ90, W-KL17, S-KL25, W-EF42, W-AB6, W-AB5 and W-AB3. Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) STA 12848+00: Stabilize fill slopes. 									W-AB3.		
Deadline: Within 72-Hour of Notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.											
	Inspe	ector Sign	natur	e: Mapshu	MA	Pillii -					
	Date	Friday	, Sep	ptember 15, 2023							



FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline**

Friday, September 15, 2023 Date:





Figure 3: STA 12825+00 - Controls in place and functioning properly.



Figure 4: MVP-RO-283 - Controls in place and functioning properly

