

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis	
Inspection Date:	Tuesday, October 3, 2023	Project Contact:	Brian Clauto, Cory Chalmers	
Spread I: Franklin County	STA 13996+56 - 14010+05 MVP-FR-306.02 MVP-FR-306.03 MVP-FR-303.01 STA 13852+46 - 13890+00	Weather:	Dry	

read I: Inklin County	MVP-FR-306.03 MVP-FR-303.01 STA 13852+46 – 13890+00	Weather:	Dry		
ACTIVE STAG	E OF CONSTRUCTION: (Check all tha	at apply)			
Tree Felling	☐ Clearing/Grubbing ☐ G	rading	hing [	☐ Stri	inging/Welding
Lowering/Backfilling	☐ Final Restoration ☐ T	emp. Stabilization	. Stabilization	⊠ Res	source Crossing
			Yes	No	N/A
	rols installed and implemented in accor t control plan and stormwater manager		and 🖂		
	ontrol measures properly maintained in d engineering practices and, where app				
3. Areas of	offsite sediment deposition observed?			$\boxtimes$	
<u>Comments:</u> II	nspected the following resources: S-KL	36, S-KL38,S-C17, W-CD5, W-C	CD6 and S-CD6		
Deadline: N	I <u>/A</u>				
condition(s) curre	ed corrective action deadline date applies to ently constitute non-compliance and/or corre ssued to the entity responsible for ensuring of	ctive actions are not completed by the			
Inspector Sig	gnature: Makshall Wil	illist			
Date: Tues	day October 3, 2023				

Page **1** of **2** 



## FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** 

Tuesday, October 3, 2023 Date:





Figure 3: Stream S-EF12 - Controls in place and functioning





