

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis		
Inspection Date:	Tuesday, October 24, 2023	Project Contact:	Brian Clauto, Cory Chalmers		
Spread I: Franklin County	STA 13915+08 - 13940+00 STA 14545+00 - 14599+24 MVP-FR-305	Weather:	Dry		

Fra	nklin County	MVP-FR-305	-	weather.		Diy			
	ACTIVE STAC	GE OF CONSTRUCTION: (Ch	neck all that a	apply)					
	Tree Felling	☐ Clearing/Grubbing ☐ Grading ☒ Trenching					☐ Stringing/Welding		
	Lowering/Backfilling	ng \square Final Restoration \boxtimes Temp. Stabilization \square Perm. Stabi						Res	ource Crossing
							Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes		
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								
	3. Areas o	f offsite sediment deposition o	bserved?					\boxtimes	
	Comments:	Inspected the following resour	rces: S-II2, S	G-G17, S-E18 and	d S-E17.				
	condition(s) curr	N/A ded corrective action deadline date rently constitute non-compliance a issued to the entity responsible fo	and/or correctiv	ve actions are not o	completed by				
	Inspector Si	ignature: Makshuu	A Will	<u>lijî</u>					
	Date: Tue:	sday, October 24, 2023							

Page 1 of 2



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 24, 2023





Figure 3: Stream S-G17 – Controls installed and properly



<u>Figure 4</u>: **STA 14562+00** – Controls installed and properly functioning.

