

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 18, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County Pittsylvania County	STA 14915+96 - 14928+52 STA 15025+00 - 15063+77	Weather:	Dry

	tsylvania County	STA 15025+00 - 15063+77			weather:		Dry	bry				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		Clearing/Grubbing	⊠ Gra	ading	\boxtimes	Trenching	☐ Stringing/Welding				
	Lowering/Backfilling	☐ F	Final Restoration	☐ Tei	mp. Stabilization		Perm. Stabilization	\boxtimes	Reso	ource Crossing		
								Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes					
	3. Areas of	offsite se	ediment deposition ob	served?				\boxtimes				
 Comments: Inspected the following resources: S-G16, S-D1-EPH, S-D2, W-D3 and S-D4. Consent Decree: (<u>Release of Sediment off ROW into Surface Waters</u>) STA 14916+00: Stream S-G16, "Strawfield Creek" (Bore Crossing). Approach for bell hole inside the 50'buffer was shot causing the stream bank to slump into the stream. This caused impacts to surface waters less than 300 LF of stream. Impact occurred on 10/17/2023 and was remediated the same day. 												
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspector Sig	ınature:	Marshali	I Will	<u>(li)</u>							

Date: Wednesday, October 18, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 18, 2023

<u>Figure 1</u>: **Stream S-G16** – Erosion matting, and seed applied to stabilize repaired bank.



Figure 2: Stream S-G16 – Evidence of minor remaining fill material within stream post remediation.



<u>Figure 3</u>: **Stream S-G16** – Erosion matting, and seed applied to stabilize repaired bank. Controls repaired and reinstalled.



<u>Figure 4</u>: **Stream S-G16** – Looking downstream under bridge crossing post remediation efforts.





FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Wednesday, October 18, 2023

