

## FIELD INSPECTION REPORT

|                                      |                                                        |                         |                             |
|--------------------------------------|--------------------------------------------------------|-------------------------|-----------------------------|
| <b>Project Name:</b>                 | Mountain Valley Pipeline                               | <b>Inspector:</b>       | Marshall Willis             |
| <b>Inspection Date:</b>              | Wednesday, October 11, 2023                            | <b>Project Contact:</b> | Brian Clauto, Cory Chalmers |
| <b>Spread I:<br/>Franklin County</b> | STA 13826+95 – 13890+00<br>MVP-FR-302<br>MVP-FR-303.01 | <b>Weather:</b>         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |                                               |                                            |                                              |                                              |                                                       |
|-----------------------------------------------|--------------------------------------------|----------------------------------------------|----------------------------------------------|-------------------------------------------------------|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading  | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding            |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- |                                                                                                                                                                                    | Yes                                 | No                                  | N/A                      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C14, S-C17, W-CD6, S-CD6 and W-CD5.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Wednesday, October 11, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, October 11, 2023

**Figure 1: Stream S-CD6** – Controls in place and functioning properly.



**Figure 2: Stream S-CD6** – Controls in place and functioning properly.



**Figure 3: Wetland W-CD5** – Controls in place and functioning properly.



**Figure 4: Stream S-C14** – Controls in place and functioning properly.

