

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, October 26, 2023	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County Franklin County</b>	STA 12973+81 – 12993+90 STA 13023+69 – 13033+59 STA 13342+67 – 13352+23 MVP-FR-292	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding  
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-KL2, S-B22, W-B25, S-G25, S-G25, W-ST2, S-RR09, and S-RR08.

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 13344+00: Secondary containment needed.

**Deadline:** Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Thursday, October 26, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, October 26, 2023

**Figure 1: Stream S-B22** – Controls installed and properly functioning.

☉ 274°W (T) ☉ 37°7'44"N, 80°8'4"W ±9ft ▲ 2673ft



**Figure 2: STA 13027+00** – Controls installed and properly functioning.

☉ 285°W (T) ☉ 37°7'30"N, 80°7'15"W ±39ft ▲ 2656ft



**Figure 3: STA 13344+00** – Secondary containment needed.

☉ 54°NE (T) ☉ 37°6'14"N, 80°2'35"W ±19ft ▲ 1583ft



**Figure 4: STA 13353+00** – Controls installed and properly functioning.

☉ 166°S (T) ☉ 37°6'8"N, 80°2'26"W ±9ft ▲ 1535ft

