



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, October 31, 2023	Project Contact:	Brian Clauto
Spread H: Montgomery	Sta 12450-12424, 13112+18- 12107+72, 12120-12126 ATWS 727, 725 AR MN279, 271	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling			☐ Clearing/Grubbing			☐ Grading		☐ Trenching		Strin	ging/Welding	
		Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Reso		ource Crossing	
									Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?											
	2.	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3.	Areas of of	fsite s	sediment deposition of	bserve	d?				\boxtimes		
Ro	C33, W-C13	s, S-M31, W- enance: (<u>72</u>	-C11 - <u>-Hour</u>	<u>r Deadline</u> from Notifi	cation)	V-AB7, W-F9PFO, S-I	NN16,	S-F15, S-MM11, S-F	16a/b,	S-		
- Sta 12120+77 CFS wattle torn and requires repair. Ineffective Controls: (24-Hour Deadline from Notification) - N/A.												
Re	ecommende	ed Correct	ive A	Action: N/A								
Deadline: Within 72-Hour of Notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible ensuring compliance on the above project.												
Ins	pector Sign	ature:		1 all noth	and the							

Page **1** of **2**

Date: Tuesday, October 31, 2023

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Tuesday, October 31, 2023

Figure 1: Sta 12120+77 CFS wattle torn and requires repair.



Figure 2: Bore site for designated crossing S-AB16, ESC's are in place.



Figure 3: Dewatering structure for designated crossing S-AB16.



Figure 4: Sta 12107+72, ESC's are in place.

