

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis Brian Clauto, Cory Chalmers			
Inspection Date:	Friday, November 17, 2023	Project Contact:				
Spread I: Franklin County	STA 13850+00 - 13863+00 STA 13934+00 - 13972+00 MVP-FR-303.01 MVP-FR-305	Weather:	Dry			

Spread I: Franklin County		STA 13934+00 - 13972+00 MVP-FR-303.01 MVP-FR-305			Weather:	eather:		Dry				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		Clearing/Grubbing		Grading		Trenching	☐ Stringing/Weldir		nging/Welding		
	Lowering/Backfilling		Final Restoration		Temp. Stabilization	\boxtimes	Perm. Stabilization		Res	ource Crossing		
								Yes	No	N/A		
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 							\boxtimes				
								\boxtimes				
	3. Areas of	offsite	sediment deposition o	bserve	d?				\boxtimes			
	Comments: I	nspecte	ed the following resour	ces: S-	C17, S-C1 and W-CD	01.						
	condition(s) curre	ed corre	ctive action deadline date estitute non-compliance a	nd/or co	rrective actions are not	comple	ted by the deadline, oth					
	actions may be is	ssued to	the entity responsible for									

Page 1 of 2



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, November 17, 2023





Figure 3: **STA 13968+00** – Controls in place and functioning properly.



<u>Figure 4</u>: **STA 13925+00** – Controls in place and functioning properly.

