

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, November 16, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14861+31 – 14928+52 STA 14776+65 – 14795+12 MVP-FR-322	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|--|---|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II9, S-II11, S-II12 and S-E28.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 14183+72: Install temp. WB per specification.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, November 16, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 16, 2023

Figure 1: Stream S-AB8 – Controls in place and functioning properly.

☉ 118°SE (T) ● 36°58'12"N, 79°39'5"W ±19ft ▲ 900ft



S-AB8
16 Nov 2023

Figure 2: Stream S-DD3 – Controls in place and functioning properly.

☉ 278°W (T) ● 36°58'8"N, 79°38'41"W ±13ft ▲ 795ft



A-DD3
16 Nov 2023

Figure 3: Stream S-G16 – Controls in place and functioning properly.

☉ 199°S (T) ● 36°58'6"N, 79°38'30"W ±13ft ▲ 777ft



S-G16
16 Nov 2023

Figure 4: STA 14183+72 – Install temp. WB per specifications.

☉ 113°SE (T) ● 36°58'44"N, 79°41'1"W ±13ft ▲ 865ft



WB

14183+72
16 Nov 2023