

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, November 2, 2023	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I:</b> Franklin County Pittsylvania County	STA 14850+00 – 14863+92 STA 15346+00 – 15260+00 STA 15595+00 – 15619+00 MVP-PI-332	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding  
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-H17, W-H6, S-A7, S-H13, W-H5, W-MM9, S-CC1, W-MMi, S-CC3 and S-P5.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Thursday, November 2, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, November 2, 2023

**Figure 1: Stream S-A7** – Controls installed and properly functioning.

☉ 270°W (T) ☉ 36°58'19"N, 79°39'44"W ±45ft ▲ 945ft



**Figure 2: Stream S-H17** – Controls installed and properly functioning.

☉ 40°NE (T) ☉ 36°58'19"N, 79°39'47"W ±13ft ▲ 933ft



**Figure 3: Stream S-H13** – Controls installed and properly functioning.

☉ 240°SW (T) ☉ 36°55'28"N, 79°30'58"W ±9ft ▲ 755ft



**Figure 4: STA 15598+00** – Controls installed and properly functioning.

☉ 282°W (T) ☉ 36°53'22"N, 79°26'6"W ±35538ft ▲ 787ft

