

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, November 14, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12942+05 – 12960+00 STA 12915+20 – 12938+19 STA 12980+00 – 12994+02 MVP-RO-288 MVP-RO-287 MVP-RO-286	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|--|--|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input checked="" type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-Y7, S-Y8, S-EF44, S-B21, W-B24, W-B25, S-B22 and S-B23.


Ineffective Controls: (24-Hour Deadline from Notification)

- STA 12929+00 to 12937+00: Install trench pipes per specification.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, November 14, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, November 14, 2023

Figure 1: Streams S-Y7 and S-Y8 – Controls installed and functioning properly.

☉ 137°SE (T) ☉ 37°8'1"N, 80°8'14"W ±26ft ▲ 2650ft



S-Y7/8
14 Nov 2023

Figure 2: Stream S-EF44 – Controls installed and functioning properly.

☉ 28°NE (T) ☉ 37°8'33"N, 80°8'18"W ±13ft ▲ 2662ft



S-EF44
14 Nov 2023

Figure 3: STA 12929+00 to 12937+00 – Install trench pipes per specification.

☉ 49°NE (T) ☉ 37°8'27"N, 80°8'21"W ±104ft ▲ 2718ft



12130
14 Nov 2023

Figure 4: STA 12929+00 to 12937+00 – Install trench pipes per specification.

☉ 187°S (T) ☉ 37°8'24"N, 80°8'23"W ±13ft ▲ 2657ft



12935
14 Nov 2023