

## FIELD INSPECTION REPORT

|   |  |                         |                             |
|---|--|-------------------------|-----------------------------|
| <b>Project Name:</b>                                    | Mountain Valley Pipeline   | <b>Inspector:</b>       | Marshall Willis             |
| <b>Inspection Date:</b>                                 | Monday, November 13, 2023  | <b>Project Contact:</b> | Brian Clauto, Cory Chalmers |
| <b>Spread H:<br/>Roanoke County<br/>Franklin County</b> | STA 13188+66 – 13198+33<br>STA 12866+36 – 12894+13<br>STA 12790+00 – 12807+43<br>MVP-FR-293.02<br>MVP-RO-283 | <b>Weather:</b>         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |  |  |  |   |   |
|--|--|--|---|---|
| <input type="checkbox"/> Tree Felling                    | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input checked="" type="checkbox"/> Trenching | <input checked="" type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization  | <input checked="" type="checkbox"/> Resource Crossing |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D10, S-D8, W-EF46, S-ST9b, W-KL48, W-KL49, S-KL55, W-KL51, S-IJ88 and S-IJ82.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Monday, November 13, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, November 13, 2023

**Figure 1: Stream S-D8** – Controls in place and functioning properly.

☉ 46°NE (T) ☉ 37°7'23"N, 80°4'28"W ±22ft ▲ 1439ft



**Figure 2: STA 12887+00** – Controls in place and functioning properly.

☉ 242°SW (T) ☉ 37°9'0"N, 80°7'55"W ±13ft ▲ 2615ft



**Figure 3: Stream S-IJ88** – Controls in place and functioning properly.

☉ 282°W (T) ☉ 37°10'4"N, 80°8'18"W ±19ft ▲ 2676ft



**Figure 4: Wetland W-IJ95** – Controls in place and functioning properly.

☉ 336°NW (T) ☉ 37°10'7"N, 80°8'17"W ±32ft ▲ 2676ft

