

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis			
Inspection Date:	Wednesday, November 8, 2023	Project Contact:	Brian Clauto, Cory Chalmers			
Spread H: Franklin County	STA 13320+00 - 13325+50 STA 13188+66 - 13197+55 STA 13411+83 - 13420+00 MVP-MLV-AR-29	Weather:	Dry			

Franklin County		STA 13188+66 - 13197+55 STA 13411+83 - 13420+00 MVP-MLV-AR-29  Weather:  Dry								
	ACTIVE STAG	E OF C	CONSTRUCTION: (Che	eck all th	nat apply)					
	Tree Felling		Clearing/Grubbing		Grading		Trenching	☐ Stringing/Weldir		nging/Welding
$\boxtimes$	Lowering/Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	$\boxtimes$	Res	ource Crossing
								Yes	No	N/A
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							$\boxtimes$		
			neasures properly main eering practices and, v					$\boxtimes$		
	3. Areas of	offsite	sediment deposition ob	served?	?				$\boxtimes$	
	<u>Comments:</u> In	nspecte	ed the following resourc	ces: S-II	9, S-II11, S-II12 and	S-E28	3.			
	Deadline: N	<u>/A</u>								
	condition(s) curre	ntly cor	ctive action deadline date stitute non-compliance ar the entity responsible for	nd/or corr	ective actions are not co	omplet	ed by the deadline, oth			
	Inspector Sig	ınatur	e: Manhall	I W	Millist .					
	Date: Wed	nesda	y, November 8, 202	3						



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

Date: Wednesday, November 8, 2023





<u>Figure 3</u>: **Stream S-D8** – Controls in place and functioning properly.



properly.

③ 111°E (T) ⑤ 37°5′34"N, 80°1′39"W ±13ft ▲ 1444ft

Figure 4: Stream S-IJ1 – Controls in place and functioning