

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, November 1, 2023	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12690+35 – 12699+00 STA 12794+32 – 12807+43 STA 12866+36 – 12890+00 MVP-RO-280 MVP-RO-283	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |  |  |  |   |   |
|--|--|--|---|---|
| <input type="checkbox"/> Tree Felling                    | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input checked="" type="checkbox"/> Trenching | <input checked="" type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization  | <input checked="" type="checkbox"/> Resource Crossing |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ88, S-IJ84, W-IJ95, W-EF46, S-St9b, W-KL48, S-KL55 and W-KL51.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Wednesday, November 1, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, November 1, 2023

**Figure 1: STA 12691+00** – Controls installed and properly functioning.

☀ 144°SE (T) ● 37°11'28"N, 80°9'24"W ±45ft ▲ 3704ft



S-C25  
01 Nov 2023

**Figure 2: STA 12699+00** – Controls installed and properly functioning.

☀ 288°W (T) ● 37°11'27"N, 80°9'19"W ±32ft ▲ 3581ft



01 Nov 2023

**Figure 3: STA 12800+00** – Controls installed and properly functioning.

☀ 356°N (T) ● 37°10'7"N, 80°8'17"W ±32ft ▲ 2664ft



12800  
01 Nov 2023

**Figure 4: Stram S-KL55** – Controls installed and properly functioning.

☀ 234°SW (T) ● 37°9'0"N, 80°7'56"W ±55ft ▲ 2649ft



A-KL55  
01 Nov 2023