

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, October 30, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12101+00 - 12110+00 STA 12119+17 - 12140+00 MVP-MN-272 MVP-MN-271	Weather:	Dry

Spread H: Montgomery County		STA 12119+17 – 12140+00 MVP-MN-272 MVP-MN-271			Weather:	Weather: Dry				
	ACTIVE STAG	E OF C	:ONSTRUCTION: (Ch	eck all t	that apply)					
	Tree Felling		Clearing/Grubbing		Grading	$\boxtimes$	Trenching		Stri	nging/Welding
$\boxtimes$	Lowering/Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	$\boxtimes$	Res	source Crossing
								Yes	No	N/A
	<ol> <li>Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?</li> <li>Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?</li> </ol>							$\boxtimes$		
								$\boxtimes$		
	3. Areas of offsite sediment deposition observed?							$\boxtimes$		
	Comments: In CD6.	nspecte	ed the following resour	ces: S-l	F15, W-F9, S-MM11,	S-C36	s, W-C12, S-C33, S-N	/M31,	S-C29	and W-
	<u>Deadline:</u> <u>N</u>	<u>/A</u>								
	condition(s) curre	ntly cor	ctive action deadline date stitute non-compliance a the entity responsible for	nd/or co	rrective actions are not c	omplet	ted by the deadline, oth			
	Inspector Siç	ınatur	e: Marshar	I A	Millio .					
	Date: Mone	day, O	ctober 30, 2023							

Page **1** of **2** 



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

Date: Monday, October 30, 2023





<u>Figure 3</u>: **STA 12120+00** – Controls installed and properly functioning.





Figure 4: STA 12137+00 – Controls installed and properly