

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 5, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12031+51 – 12035+75 STA 12420+73 – 12435+16 STA 12445+19 – 12464+25 MVP-MN-268 MVP-MN-279	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G36, S-G38. S-G39, S-PP23, S-G40, S-NN16, S-CD12b and W-KL58.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, December 5, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 5, 2023

Figure 1: Stream S-NN16 – Controls installed and functioning properly.

☉ 210°SW (T) ☉ 37°14'1"N, 80°11'51"W ±13ft ▲ 1178ft



Figure 2: STA 12434+00 – Controls installed and functioning properly.

☉ 322°NW (T) ☉ 37°14'2"N, 80°11'48"W ±19ft ▲ 1194ft



Figure 3: Wetland W-KL58 – Controls installed and functioning properly.

☉ 48°NE (T) ☉ 37°13'44"N, 80°12'11"W ±45ft ▲ 1205ft



Figure 4: ATWS 645 – Controls installed and functioning properly.

☉ 258°W (T) ☉ 37°13'50"N, 80°11'51"W ±13ft ▲ 1237ft

