

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, November 29, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12070+00 – 12155+00 MVP-MN-270	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, S-F16A/B, S-C36, S-MM31, S-C29, W-C6 and W-C5.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: **Wednesday, November 29, 2023**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, November 29, 2023

Figure 1: STA 12090+00 – Controls installed and functioning properly.

☉ 272°W (T) ☉ 37°14'5"N, 80°15'56"W ±7168ft ▲ 1480ft



Figure 2: STA 12116+00 – Controls installed and functioning properly.

☉ 120°SE (T) ☉ 37°14'13"N, 80°15'56"W ±6902ft ▲ 1444ft



Figure 3: STA 12137+00 – Controls installed and functioning properly.

☉ 105°E (T) ☉ 37°15'22"N, 80°16'35"W ±144ft ▲ 1457ft



Figure 4: STA 12153+00 – Controls installed and functioning properly.

☉ 94°E (T) ☉ 37°15'17"N, 80°16'16"W ±68ft ▲ 1509ft

