

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 13, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14233+57 – 14249+19 STA 14411+09 – 14454+22 MVP-MLV-AR-32 MVP-FR-315	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|---|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F11, S-C19, S-GH36, S-KL17, S-GH37, S-GH9, S-GH40, S-GH44 and W-GH44.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, December 13, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 13, 2023

Figure 1: Stream S-F11 – Controls installed and functioning properly.

☉ 113°SE (T) ☉ 37°3'10"N, 79°49'33"W ±45ft ▲ 933ft



14249 s-F11
13 Dec 2023

Figure 2: STA 14428+00 – Controls installed and functioning properly.

☉ 312°NW (T) ☉ 37°1'46"N, 79°46'36"W ±19ft ▲ 1150ft



14428
13 Dec 2023

Figure 3: Stream S-GH44 – Controls installed and functioning properly.

☉ 107°E (T) ☉ 37°1'42"N, 79°46'24"W ±29ft ▲ 1192ft



S-Gh44
13 Dec 2023

Figure 4: STA 14454+00 – Controls installed and functioning properly.

☉ 299°NW (T) ☉ 37°1'30"N, 79°46'17"W ±387ft ▲ 1126ft



14454
13 Dec 2023