

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 21, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13811+81 – 13875+73 MVP-FR-302 MVP-FR-303.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|--|--|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☒ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☐ Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C14, S-C16, S-C17, W-CD6 and S-CD6.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, December 21, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 21, 2023

Figure 1: STA 13818+00 – Controls installed and functioning properly.

☉ 298°NW (T) ● 37.068252°N, 79.922281°W ±39ft ▲ 1118ft



Figure 2: STA 13833+00 – Controls installed and functioning properly.

☉ 180°S (T) ● 37.064448°N, 79.922008°W ±16ft ▲ 1112ft



Figure 3: Stream S-CD6 – Controls installed and functioning properly.

☉ 151°SE (T) ● 37.057709°N, 79.913921°W ±9ft ▲ 1017ft



Figure 4: STA 13852+00 – Controls installed and functioning properly.

☉ 13°N (T) ● 37.059152°N, 79.921134°W ±26ft ▲ 1114ft

