

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis Brian Clauto, Cory Chalmers			
Inspection Date:	Monday, December 18, 2023	Project Contact:				
Spread I: Franklin County	STA 14233+57 - 14249+19 MVP-MLV-AR-32	Weather:	Wet			

Fra	nklin County	MVP-MLV-AR-32		weather.		Wet			
	ACTIVE STAG	E OF CONSTRUCTION: (Che	eck all that a	apply)					
	Tree Felling	☐ Clearing/Grubbing	☐ Gra	ding	☐ Tr	enching		Stri	nging/Welding
	Lowering/Backfilling	☐ Final Restoration	☐ Tem	Temp. Stabilization   Perm. Stabilization			$\boxtimes$	Res	ource Crossing
							Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								
	3. Areas of	offsite sediment deposition of	oserved?					$\boxtimes$	
	<u>Comments:</u> In	nspected the following resource	ces: S-F11 a	and S-C19.					
	condition(s) curre	I/A  ed corrective action deadline date ently constitute non-compliance are essued to the entity responsible for	nd/or correctiv	ve actions are not c	ompleted b	by the deadline, other			
	Inspector Sig	Marshar	l Will	<u> </u>	, ,				



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

<u>Date</u>: Monday, December 18, 2023





<u>Figure 3</u>: **ATWS 351** – Controls installed and functioning properly.



<u>Figure 4</u>: **ATWS 351A** – Controls installed and functioning properly.

