

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 26, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	MVP-MN-270.01/271/272 MVP-MN-273/274/275	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C21.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, January 26, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 26, 2024

Figure 1: STA 12102+00 – Controls in place and functioning properly.

☉ 232°SW (T) ● 37.258427°N, 80.287817°W ±164ft ▲ 1385ft



Figure 2: STA 12110+00 – Controls in place and functioning properly.

☉ 288°W (T) ● 37.258119°N, 80.285048°W ±22ft ▲ 1437ft



Figure 3: STA 12118+00 – Controls in place and functioning properly.

☉ 298°NW (T) ● 37.257233°N, 80.282640°W ±55ft ▲ 1420ft



Figure 4: STA 12153+00 – Controls in place and functioning properly.

☉ 113°SE (T) ● 37.254938°N, 80.270919°W ±13ft ▲ 1547ft

