

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 22, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14233+00 – 14250+00 MVP-MLV-AR-32	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-F11 and S-C19.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, January 22, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 22, 2024

Figure 1: Stream S-F11 – Controls in place and functioning properly.

☉ 77°E (T) ☉ 37.052795°N, 79.825821°W ±22ft ▲ 860ft



Figure 2: Stream S-F11 – Controls in place and functioning properly.

☉ 110°E (T) ☉ 37.052948°N, 79.825984°W ±22ft ▲ 849ft



Figure 3: Stream S-C19 – Controls in place and functioning properly.

☉ 255°W (T) ☉ 37.054830°N, 79.829077°W ±39ft ▲ 852ft



Figure 4: Stream S-C19 – Controls in place and functioning properly.

☉ 179°S (T) ☉ 37.054821°N, 79.828903°W ±22ft ▲ 904ft

