

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 19, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13958+31 – 14000+00 STA 14233+00 – 14240+00 MVP-MLV-AR-32	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL35, W-EF48 and S-C19.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, January 19, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 19, 2024

Figure 1: STA 13959+00 – Controls in place and functioning properly.

☉ 109°E (T) ☉ 37.046243°N, 79.894886°W ±219ft ▲ 1120ft



13959
19 Jan 2024

Figure 2: Stream S-KL35 – Controls in place and functioning properly.

☉ 240°SW (T) ☉ 37.052202°N, 79.886135°W ±22ft ▲ 1015ft



S-KL35
19 Jan 2024

Figure 3: Stream S-C19 – Controls in place and functioning properly.

☉ 154°SE (T) ☉ 37.054854°N, 79.828976°W ±13ft ▲ 887ft



Magodee
19 Jan 2024

Figure 4: Stream S-C19 – Controls in place and functioning properly.

☉ 81°E (T) ☉ 37.054862°N, 79.828950°W ±13ft ▲ 889ft



Magodee
19 Jan 2024