

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, February 2, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County Roanoke County	MVP-MN-268 MVP-MN268.01 MVP-RO-278.01 STA 12030+00 – 12033+00 STA 12543+00 – 12546+00	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G36, S-G39, S-EF54, S-EF20 and W-EF5.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, February 2, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, February 2, 2024

Figure 1: Stream S-G39 – Controls in place and functioning properly.

☉ 163°S (T) ☉ 37.264796°N, 80.308624°W ±13ft ▲ 1750ft



Figure 2: MVP-RO-278.01 – Controls in place and functioning properly.

☉ 188°S (T) ☉ 37.217036°N, 80.188573°W ±52ft ▲ 1489ft



Figure 3: Stream S-EF20a – Controls in place and functioning properly.

☉ 45°NE (T) ☉ 37.211026°N, 80.193368°W ±32ft ▲ 1613ft



Figure 4: Stream S-EF20a – Controls in place and functioning properly.

☉ 299°NW (T) ☉ 37.210878°N, 80.193376°W ±13ft ▲ 1492ft

