

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, February 8, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	MVP-MLV-AR-32 STA 14230+00 – 14249+00	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Resource Crossing

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-C19 and S-F11.

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 14233+80: Properly install curlex along stream S-C19. Fabric is not keyed properly.

**Deadline:** Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_



**Date:** Thursday, February 8, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, February 8, 2024

**Figure 1: Stream S-C19** – Curlex improperly installed. Edges should be keyed in per the approved details.

☉ 229°SW (T) ● 37.055365°N, 79.829942°W ±16ft ▲ 886ft



**Figure 2: Stream S-C19** – Curlex improperly installed. Edges should be keyed in per the approved details.

☉ 71°E (T) ● 37.055322°N, 79.830046°W ±13ft ▲ 865ft



**Figure 3: Stream S-C19** – Curlex improperly installed. Edges should be keyed in per the approved details.

☉ 250°W (T) ● 37.055317°N, 79.829989°W ±16ft ▲ 865ft



**Figure 4: Stream S-F11** – Controls in place and functioning properly.

☉ 109°E (T) ● 37.053090°N, 79.825985°W ±55ft ▲ 870ft

