

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, February 5, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	MVP-MLV-AR-32 STA 14233+00 – 14240+00	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C19.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, February 5, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, February 5, 2024

Figure 1: STA 14233+00 – Controls in place and functioning properly.

☉ 243°SW (T) ☉ 37.055266°N, 79.830008°W ±13ft ▲ 879ft



Figure 2: Stream S-C19 – Controls in place and functioning properly.

☉ 200°S (T) ☉ 37.055304°N, 79.829979°W ±9ft ▲ 838ft



Figure 3: Stream S-C19 – Controls in place and functioning properly.

☉ 234°SW (T) ☉ 37.054901°N, 79.829160°W ±49ft ▲ 871ft



Figure 4: Stream S-C19 – Controls in place and functioning properly.

☉ 265°W (T) ☉ 37.055395°N, 79.829375°W ±13ft ▲ 862ft

