

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 29, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14070+00 - 14105+26 MVP-FR-309.05 MVP-FR-309.06	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	ıg		Clearing/Grubbing		Grading		Trenching		Strir	nging/Welding	
	Lowering/E	g/Backfilling \square Final Restoration \square Temp. Stabilization $oxtimes$ Perm. Stabilizatio		Perm. Stabilization	n 🗵 Dormant							
									Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							erosion and	\boxtimes			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes				
	3. Areas of offsite sediment deposition observed?								\boxtimes			
	Comments: Inspected the following resources: S-KL41 Routine Maintenance: (72-Hour Deadline from Notification) - STA 14102+00 to 14104+00: Repair rilling. Restabilize and reseed as needed. - STA 14082+00 to 14083+00: Repair rilling. Restabilize and reseed as needed. - STA 14075+00 to 14177+00: Repair rilling. Restabilize and reseed as needed. Ineffective Controls: (24-Hour Deadline from Notification) - STA 14102+00 to 14104+00: CFS undermined at several locations. - STA 14082+00 to 14083+00: CFS undermined at several locations. - STA 14075+00 to 14177+00: CFS undermined at several locations.											

<u>Deadline:</u> <u>Various - See Comments</u>

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, January 29, 2024



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, January 29, 2024

<u>Figure 1</u>: **STA 14102+00 to 14104+00** – CFS undermined. Maintenance needed.



Figure 2: STA 14102+00 to 14104+00 – Repair rilling. Restabilize and reseed as needed.



Figure 3: STA 14082+00 to 14083+00 – CFS undermined. Maintenance needed.



Figure 4: STA 14082+00 to 14083+00 – Repair rilling. Restabilize and reseed as needed.





FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, January 29, 2024

