



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, February 27, 2024	Project Contact:	Brian Clauto
Spread H: Montgomery	Sta 12030-12038, 12117, 12190- 12200 ATWS 474, 703, 1375, 1446, 725 AR MN268 01, 279	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling	Free Felling ☐ Clearing/Grubbing ☐ Grading ☐			Trenching		Stringing/Welding					
	Lowering/B	Backfilling		Final Grading		Temp. Stabilization	oilization \square Perm. Stabilization $oxtimes$ Resource C		ce Crossing			
									Yes	No N/A	Ą	
	1.			alled and implemented plan and stormwater		cordance with the appr gement plans?	oved	erosion and	\boxtimes			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes					
	3.	Areas of o	ffsite s	sediment deposition of	oserve	d?						
 Comments: Inspected the following resources: S-G39, S-G40, S-PP23, W-PP8, S-G38, S-G36, S-C21, S-0011, S-NN16 Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) N/A. Recommended Corrective Action: N/A 												
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:												

Tuesday, February 27, 2024

Date:

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, February 27, 2024

Figure 1: Designated crossing S-G39, ESC's devices in place.





<u>Figure 3</u>: Sta 12038, area is stabilized, and ESC's devices are in place.



Figure 4: Sta 12117, area is stabilized, and ESC's devices are in place.

