

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 1, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14230+00 - 14249+00 MVP-MLV-AR-32	Weather:	Wet

Fra	nklin County	/	MVP-	MLV-AR-32								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling			Clearing/Grubbing	earing/Grubbing		ding		Trenching	☐ Stringing/Welding		
	Lowering/Ba	ackfilling		Final Restoration	\boxtimes	Tem	p. Stabilization		Perm. Stabilization	\boxtimes	□ Resource Crossin	
										Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?									\boxtimes		
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									\boxtimes		
	3.	Areas of o	offsite s	sediment deposition	observe	d?					\boxtimes	
	Com	<i>ments:</i> Ins	specte	ed the following resou	ırces: S	-C19 a	and S-F11.					
	<u>Dead</u>	<u>line:</u> N/	<u>A</u>									
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspe	ctor Sigi	nature	e: Marshu	U A	file						
	Date:	Friday	, Mar	rch 1, 2024								



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline





Date: Friday, March 1, 2024

<u>Figure 3</u>: **Stream S-C19** – Controls installed and functioning properly.



Figure 4: **Stream S-F11** – Controls installed and functioning properly.

