

FIELD INSPECTION REPORT

| | | | |
|------------------------------|--|------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Friday, February 23, 2024 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I: Franklin County | STA 14230+00 – 14249+00 MVP-MLV-AR-32 | Weather: | Wet |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|--------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C19 and S-F11.

Ineffective Controls: (24-Hour Deadline from Notification)

- Magodee Creek (S-C19): Retrieve sediment discharges impacting resource and sediment deposited off LOD in upland areas. Sediment deposit caused from bank failure and overwhelming of dewatering structure for S-F11.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, February 23, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, February 23, 2024

Figure 1: Stream S-C19 – Bank failure caused by dewatering structure. Sediment deposited with Magodee Creek.

☉ 303°NW (T) ● 37.053967°N, 79.828797°W ±13ft ▲ 864ft



Figure 2: Stream S-C19 – Bank failure caused by dewatering structure. Sediment deposited with Magodee Creek.

☉ 304°NW (T) ● 37.053802°N, 79.828856°W ±13ft ▲ 853ft



Figure 3: Stream S-C19 – Sediment deposited off ROW from overwhelmed dewatering structures for S-F11.

☉ 304°NW (T) ● 37.053998°N, 79.828747°W ±13ft ▲ 861ft



Figure 4: Stream S-C19 – Sediment deposited off ROW from overwhelmed dewatering structures for S-F11.

☉ 150°SE (T) ● 37.054592°N, 79.828991°W ±9ft ▲ 883ft

