

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 21, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14230+00 – 14249+00 MVP-MLV-AR-32	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|--------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C19 and S-F11.

Ineffective Controls: (24-Hour Deadline from Notification)

- Blackwater River (S-F11): Retrieve sediment impacting resource. Sediment deposit caused from bank failure down gradient of dewatering structure.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, February 21, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 21, 2024

Figure 1: Stream S-C19 – Controls in place and functioning properly.

☉ 301°NW (T) ☉ 37.052664°N, 79.825536°W ±32ft ▲ 867ft



Figure 2: Stream S-C19 – Controls in place and functioning properly.

☉ 219°SW (T) ☉ 37.054733°N, 79.828903°W ±13ft ▲ 882ft



Figure 3: Stream S-F11 – Sediment deposited into the Blackwater River downstream of the ROW crossing. Caused by bank failure due to dewatering operations.

☉ 2°N (T) ☉ 37.054030°N, 79.826193°W ±13ft ▲ 858ft



Figure 4: Stream S-F11 – Bank failure down gradient of the dewatering operation.

☉ 315°NW (T) ☉ 37.054060°N, 79.826242°W ±16ft ▲ 866ft

