

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 22, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12543+00 – 12549+00 MVP-MN-278.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF54, W-EF5 and S-EF20A.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, February 22, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 22, 2024

Figure 1: Wetland W-EF5 – Controls in place and functioning properly.

☉ 107°E (T) ● 37.210902°N, 80.193335°W ±19ft ▲ 1493ft



Figure 2: STA 12543+00 – Controls in place and functioning properly.

☉ 259°W (T) ● 37.210990°N, 80.193318°W ±16ft ▲ 1483ft



Figure 3: STA 12543+00 – Controls in place and functioning properly.

☉ 310°NW (T) ● 37.210884°N, 80.193478°W ±13ft ▲ 1480ft



Figure 4: MVP-MN-278.01 – Controls in place and functioning properly along access road.

☉ 8°N (T) ● 37.216444°N, 80.188636°W ±98ft ▲ 1486ft

