

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, March 12, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 13784+00 – 13853+45 MVP-FR-300 MVP-FR-303.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |  |   |   |
|---|--|--|---|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching                      | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |


- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D23, S-D22, S-D20, S-C14 and S-C16.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Tuesday, March 12, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, March 12, 2024

**Figure 1: STA 13790+00** – Controls in place and functioning properly.

☉ 245°SW (T) ● 37.070342°N, 79.931299°W ±22ft ▲ 993ft



13790  
12 Mar 2024

**Figure 2: STA 13813+00** – Controls in place and functioning properly.

☉ 106°E (T) ● 37.069027°N, 79.923924°W ±16ft ▲ 1132ft



13813  
12 Mar 2024

**Figure 3: Stream S-C14** – Controls in place and functioning properly.

☉ 164°S (T) ● 37.064108°N, 79.922038°W ±13ft ▲ 1059ft



A-C14  
12 Mar 2024

**Figure 4: STA 13826+00** – Controls in place and functioning properly.

☉ 200°S (T) ● 37.066055°N, 79.921887°W ±13ft ▲ 1125ft



13826  
12 Mar 2024