

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 3, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12938+19 – 12960+00 MVP-RO-287	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-IJ36, S-IJ43, S-Y9, S-Y8 and S-Y7.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, April 3, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 3, 2024

Figure 1: Stream S-IJ43 – Controls installed and functioning properly.

☉ 73°E (T) ● 37.138833°N, 80.139786°W ±91ft ▲ 2736ft



Figure 2: Wetland W-IJ36 – Controls installed and functioning properly.

☉ 1°N (T) ● 37.138699°N, 80.139865°W ±22ft ▲ 2559ft



Figure 3: STA 12935+00 – Controls installed and functioning properly.

☉ 16°N (T) ● 37.139407°N, 80.140240°W ±32ft ▲ 2576ft



Figure 4: STA 12956+00 – Controls installed and functioning properly.

☉ 180°S (T) ● 37.134561°N, 80.137583°W ±9ft ▲ 2642ft

