

## FIELD INSPECTION REPORT

|                                      |  |                         |                             |
|--------------------------------------|--|-------------------------|-----------------------------|
| <b>Project Name:</b>                 | Mountain Valley Pipeline                               | <b>Inspector:</b>       | Marshall Willis             |
| <b>Inspection Date:</b>              | Thursday, April 11, 2024                               | <b>Project Contact:</b> | Brian Clauto, Cory Chalmers |
| <b>Spread I:<br/>Franklin County</b> | STA 13820+00 – 13863+01<br>MVP-FR-302<br>MVP-FR-303.01 | <b>Weather:</b>         | Rainy                       |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |  |  |   |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C14, S-C16 and S-C17.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, April 11, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, April 11, 2024

**Figure 1: ATWS 1040** – Controls in place and functioning properly.

☉ 63°NE (T) ● 37.058675°N, 79.922078°W ±98ft ▲ 1021ft



**Figure 2: STA 13852+00** – Controls in place and functioning properly.

☉ 2°N (T) ● 37.059173°N, 79.921064°W ±13ft ▲ 1138ft



**Figure 3: STA 13860+00** – Controls in place and functioning properly.

☉ 110°E (T) ● 37.058770°N, 79.919345°W ±29ft ▲ 1110ft



**Figure 4: STA 13831+00** – Controls in place and functioning properly.

☉ 185°S (T) ● 37.064500°N, 79.921735°W ±39ft ▲ 1079ft

