

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, April 5, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14018+47 – 14062+17 MVP-MLV-AR-31	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL39, S-YZ5 and S-YZ4.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14052+58: Repair rills and restabilize denuded areas.
- STA 14039+00: Repair rills and restabilize denuded areas.
-

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Friday, April 5, 2024**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 5, 2024

Figure 1: STA 14039+00 – Repair rilling and restabilize denuded areas.

☉ 282°W (T) ☉ 37.061939°N, 79.879299°W ±9ft ▲ 1090ft



Figure 2: STA 14052+00 – Repair rilling and restabilize denuded areas.

☉ 258°W (T) ☉ 37.065331°N, 79.877775°W ±13ft ▲ 1144ft



Figure 3: STA 14049+00 – Controls in place and functioning properly.

☉ 5°N (T) ☉ 37.064233°N, 79.878123°W ±9ft ▲ 1182ft



Figure 4: STA 14030+00 – Controls in place and functioning properly.

☉ 62°NE (T) ☉ 37.060597°N, 79.880899°W ±16ft ▲ 1085ft

