

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 4, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15063+85 – 15142+66 MVP-PI-325	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G22, S-G21, S-G23 and S-G20.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 15080+00 to 15081+00: Repair rills and restabilize denuded areas.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, April 4, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 4, 2024

Figure 1: STA 15080+00 to 15081+00 – Repair rilling and restabilize denuded areas.

☉ 303°NW (T) ● 36.961933°N, 79.588018°W ±13ft ▲ 896ft



Figure 2: STA 15070+00 – Controls installed and functioning properly.

☉ 122°SE (T) ● 36.962684°N, 79.591533°W ±22ft ▲ 926ft



Figure 3: STA 15103+00 – Controls installed and functioning properly.

☉ 166°S (T) ● 36.958074°N, 79.583590°W ±59ft ▲ 809ft



Figure 4: Stream S-A6 – Controls installed and functioning properly.

☉ 172°S (T) ● 36.952392°N, 79.580514°W ±13ft ▲ 872ft

