

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, May 8, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I:</b> Franklin County Pittsylvania County	STA 13437+75 – 13493+14 STA 14220+00 – 14231+00 STA 15430+00 – 15480+67 MVP-FR-293.02 MVP-FR-311	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |   |  |   |  |
|---|---|--|---|--|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing            | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching                      | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant           |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ8, S-C20, S-G3 and S-CC16.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Wednesday, May 8, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, May 8, 2024

**Figure 1: STA 13441+00** – Controls in place and functioning properly.

☉ 89°E (T) ● 37.089921°N, 80.019647°W ±13ft ▲ 1691ft



**Figure 2: STA 13490+00** – Controls in place and functioning properly.

☉ 86°E (T) ● 37.087845°N, 80.006819°W ±187ft ▲ 1331ft



**Figure 3: Stream S-G3** – Controls in place and functioning properly.

☉ 114°SE (T) ● 36.915795°N, 79.490172°W ±16ft ▲ 796ft



**Figure 4: STA 14230+00** – Controls in place and functioning properly.

☉ 63°NE (T) ● 37.054956°N, 79.831232°W ±13ft ▲ 1011ft

