

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, May 7, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12190+85 – 12204+00 STA 12135+53 – 12145+00 MVP-MN-272 MVP-MN-275	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C21, S-OO11, W-C5 and W-C6.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, May 7, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 7, 2024

Figure 1: Stream S-C21 – Controls in place and functioning properly at Bradshaw Creek.

☉ 31°NE (T) ● 37.236142°N, 80.265021°W ±6791ft ▲ 1350ft



Figure 2: STA 12201+00 – Controls in place and functioning properly.

☉ 72°E (T) ● 37.252183°N, 80.256738°W ±55ft ▲ 1346ft



Figure 3: STA 12140+00 – Controls in place and functioning properly.

☉ 127°SE (T) ● 37.256212°N, 80.276265°W ±22ft ▲ 1450ft



Figure 4: STA 12135+00 – Controls in place and functioning properly.

☉ 285°W (T) ● 37.256096°N, 80.276759°W ±13ft ▲ 1437ft

