



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, May 13, 2024	Project Contact:	Brian Clauto
Spread I: Franklin	Sta 13440, 13497-13498, 14235- 14250 FR 293.02, MLV AR32 ATWS 693, 350, 351, 351a	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	g		Clearing/Grubbing		Grading		Trenching		String	ging/Welding	
	Lowering/E	Backfilling	\boxtimes	Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	□ Dormant			
									Yes	No I	N/A	
	1.			alled and implemented I plan and stormwater r		cordance with the appr gement plans?	oved	erosion and				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?											
	3.	Areas of of	fsite s	sediment deposition ob	serve	d?				\boxtimes		
•	<u>Comments:</u>	Inspected to	he fol	lowing resources: S-IJ	10, W	-IJ6, S-C19, S-F11						
Routine Maintenance: (72-Hour Deadline from Notification) - N/A Ineffective Controls: (24-Hour Deadline from Notification) - Sta 13498 no perimeter controls, follow construction sequence before land disturbance begins - Sta 13497 no construction entrance at Cahas 2, CE was removed before land disturbance was completed. Do not remove CE before land disturbance is completed. Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.												
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:												
Date: Monday, May 13, 2024												



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, May 13, 2024

Figure 1: Sta 13340, perimeter controls in place.



<u>Figure 2</u>: Designated crossing S-C19, ESC and permanent measures in place.



<u>Figure 3</u>: Designated crossing S-IJ10 and W-IJ 6, perimeter controls not in place during active construction.



Figure 4: Near St 13498, CE was not in place.

