

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 30, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13437+75 – 13541+66 MVP-FR-293.02	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☒ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ8, S-IJ6, S-IJ10, S-KL2, W-II8 and S-II7.

**Routine Maintenance:** (*72-Hour Deadline from Notification*)

- STA 13519+50: Re-stabilize denuded area.
- STA 13533+00: Re-stabilize denuded area.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, May 30, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, May 30, 2024

**Figure 1: STA 13444+00** – Controls in place and functioning properly.

☉ 125°SE (T) ☉ 37.089502°N, 80.019077°W ±134ft ▲ 1457ft



13444  
30 May 2024

**Figure 2: Stream S-KL2** – Controls in place and functioning properly.

☉ 64°NE (T) ☉ 37.090323°N, 79.996385°W ±9ft ▲ 1239ft



S-KL2  
30 May 2024

**Figure 3: STA 13519+50** – Restabilize denuded area at final grade.

☉ 257°W (T) ☉ 37.090357°N, 79.997537°W ±9ft ▲ 1269ft



Restabilize 72

13519+50  
30 May 2024

**Figure 4: STA 13533+00** – Restabilize denuded area at final grade.

☉ 93°E (T) ☉ 37.091535°N, 79.993857°W ±13ft ▲ 1294ft



Restabilize above S-118 (72)

13533  
30 May 2024