

FIELD INSPECTION REPORT

| | | | |
|--------------------------------------|---------------------------------------------------------------------|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Tuesday, May 21, 2024 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I: Franklin County | STA 13435+00 – 13450+00 STA 13530+00 – 13550+00 MVP-FR-293.02 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|-----------------------------------------------|-------------------------------------------------------|----------------------------------------------|---------------------------------------------------------|---------------------------------------------|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II8, S-II7, W-II8 and S-II9.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, May 21, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 21, 2024

Figure 1: STA 13441+00 – Controls in place and functioning properly.

☉ 134°SE (T) ● 37.090502°N, 80.020111°W ±65ft ▲ 1678ft



Figure 2: MVP-FR-293.02 – Controls in place and functioning properly.

☉ 10°N (T) ● 37.090823°N, 80.020250°W ±9ft ▲ 1714ft



Figure 3: STA 13541+00 – Controls in place and functioning properly.

☉ 272°W (T) ● 37.091290°N, 79.991245°W ±9ft ▲ 1320ft

