

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, May 22, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12955+00 – 12960+00 STA 12915+00 – 12938+00 MVP-RO-287 MVP-RO-286	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |   |  |   |   |
|---|---|--|---|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing            | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching                      | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-Y7, S-Y8, S-EF44 and W-EF44.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Wednesday, May 22, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, May 22, 2024

**Figure 1: Stream S-Y8** – Controls in place and functioning properly.

☉ 87°E (T) ☉ 37.134187°N, 80.137537°W ±9ft ▲ 2633ft



S-Y8  
22 May 2024

**Figure 2: STA 12956+00** – Controls in place and functioning properly.

☉ 325°NW (T) ☉ 37.135047°N, 80.137926°W ±13ft ▲ 2669ft



12956  
22 May 2024

**Figure 3: Stream S-EF44** – Controls in place and functioning properly.

☉ 230°SW (T) ☉ 37.143035°N, 80.138306°W ±9ft ▲ 2642ft



A-EF44  
22 May 2024

**Figure 4: STA 12935+00** – Controls in place and functioning properly.

☉ 223°SW (T) ☉ 37.140098°N, 80.139655°W ±19ft ▲ 2635ft



12935  
22 May 2024