

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, June 6, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12186+92 – 12201+00 STA 12409+03 – 12437+00 MVP-MN-274/275 MVP-MN-279.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
☒ Perm. Stabilization
☐ Other

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-OO11, S-C21 and S-NN16.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, June 6, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, June 6, 2024

Figure 1: STA 12200+00 – Controls in place and functioning properly.

☉ 39°NE (T) ☉ 37.252074°N, 80.257022°W ±32ft ▲ 1335ft



Figure 2: MVP-MN-275 – Controls in place and functioning properly.

☉ 273°W (T) ☉ 37.252065°N, 80.257487°W ±19ft ▲ 1397ft



Figure 3: Stream S-C21 – Controls in place and functioning properly.

☉ 77°E (T) ☉ 37.251847°N, 80.259202°W ±19ft ▲ 1244ft



Figure 4: STA 12420+00 – Controls in place and functioning properly.

☉ 346°N (T) ☉ 37.236609°N, 80.199497°W ±13ft ▲ 1191ft

