

## FIELD INSPECTION REPORT

|                              |                          |                  |                             |
|------------------------------|--------------------------|------------------|-----------------------------|
| Project Name:                | Mountain Valley Pipeline | Inspector:       | Marshall Willis             |
| Inspection Date:             | Thursday, June 27, 2024  | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I:<br>Franklin County | STA 13575+21 – 13644+82  | Weather:         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II6 and S-E28.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, June 27, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, June 27, 2024

**Figure 1: STA 13575+00** – Controls in place and functioning properly.

☉ 276°W (T) ● 37.092735°N, 79.979941°W ±72ft ▲ 1325ft



13575  
27 Jun 2024

**Figure 2: STA 13590+00** – Controls in place and functioning properly.

☉ 137°SE (T) ● 37.092935°N, 79.975405°W ±42ft ▲ 1450ft



13590  
27 Jun 2024

**Figure 3: STA 13620+00** – Controls in place and functioning properly.

☉ 63°NE (T) ● 17 N 591676 4105320 ±13ft ▲ 1368ft



13620  
27 Jun 2024

**Figure 4: STA 13632+00** – Controls in place and functioning properly.

☉ 226°SW (T) ● 17 N 592021 4105426 ±49ft ▲ 1299ft



13632  
27 Jun 2024