

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, June 24, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12000+00 – 12036+00 STA 12374+00 – 12410+00 MVP-MN-268/268.01 MVP-MLV-AR-27	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|---|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☒ Final Restoration | ☐ Temp. Stabilization | ☒ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-PP23, S-G40, S-G39, S-G38, S-G39, S-G36, S-OO16 and S-NN19.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, June 24, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 24, 2024

Figure 1: STA 12007+00 – Controls in place and functioning properly.

☉ 237°SW (T) ● 37.269279°N, 80.314228°W ±42ft ▲ 1528ft



Figure 2: STA 12037+00 – Controls in place and functioning properly.

☉ 137°SE (T) ● 37.264887°N, 80.307008°W ±9ft ▲ 1727ft



Figure 3: MLV-27 – Controls in place and functioning properly.

☉ 158°S (T) ● 37.240020°N, 80.199373°W ±85ft ▲ 1403ft



Figure 4: STA 12400+00 – Controls in place and functioning properly.

☉ 299°NW (T) ● 37.241274°N, 80.201988°W ±29ft ▲ 1452ft

