

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 10, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13140+00 – 13197+55 MVP-FR-292 MVP-FR-292.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|---|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☒ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-D13, S-D12, S-D11, S-D8 and S-D10.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, July 10, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 10, 2024

Figure 1: STA 13142+00 – Controls in place and functioning properly.

☉ 62°NE (T) ● 17 N 581145 4108735 ±164ft ▲ 1616ft



Figure 2: Stream S-D11 – Controls in place and functioning properly.

☉ 209°SW (T) ● 17 N 581188 4109046 ±29ft ▲ 1663ft



Figure 3: STA 13165+00 – Controls in place and functioning properly.

☉ 63°NE (T) ● 17 N 581401 4109177 ±16ft ▲ 1701ft



Figure 4: Stream S-D8 – Controls in place and functioning properly.

☉ 149°SE (T) ● 17 N 582192 4108936 ±9ft ▲ 1444ft

