

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 3, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10505+00 – 10537+00 MVP-GI-234 MVP-GI-235 MVP-GI-236	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
☒ Temp. Stabilization
☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-Q12 and S-Q13.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, July 3, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 3, 2024

Figure 1: STA 10523+00 – Controls in place and functioning properly.

☉ 44°NE (T) ● 17 N 528044 4136392 ±13ft ▲ 2013ft



Figure 2: STA 10536+00 – Controls in place and functioning properly.

☉ 12°N (T) ● 17 N 527905 4136052 ±13ft ▲ 1929ft



Figure 3: STA 10505+00 – Controls in place and functioning properly.

☉ 4°N (T) ● 17 N 528365 4136676 ±9ft ▲ 2085ft



Figure 4: STA 10502+00 – Controls in place and functioning properly.

☉ 301°NW (T) ● 17 N 528307 4136611 ±13ft ▲ 2043ft

