

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, July 1, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12725+00 – 12743+00 STA 12990+00 – 12995+00 MVP-RO-288 MVP-RO-287 MVP-RO-281	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |   |   |  |
|---|--|---|---|--|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading                        | <input type="checkbox"/> Trenching                      | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant           |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-B21, W-B24, S-Y7, S-Y8 and S-EF65

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Monday, July 1, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, July 1, 2024

**Figure 1: STA 12972+00** – Controls in place and functioning properly.

☉ 283°W (T) ☉ 17 N 576670 4109692 ±52ft ▲ 2698ft



12972  
01 Jul 2024

**Figure 2: STA 12994+00** – Controls in place and functioning properly.

☉ 78°E (T) ☉ 17 N 577238 4109494 ±9ft ▲ 2659ft



12994  
01 Jul 2024

**Figure 3: STA 12727+00** – Controls in place and functioning properly.

☉ 316°NW (T) ☉ 17 N 575467 4115803 ±42ft ▲ 3389ft



12727  
01 Jul 2024

**Figure 4: STA 12743+00** – Controls in place and functioning properly.

☉ 157°SE (T) ☉ 17 N 575524 4115353 ±13ft ▲ 3001ft



12743  
01 Jul 2024