

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, July 15, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 14310+00 – 14311+00 MVP-FR-313.01 MVP-FR-315 STA 14524+00 – 14525+00	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☐ Grading     
 ☐ Trenching     
 ☐ Stringing/Welding  
☐ Lowering/Backfilling     
 ☐ Final Restoration     
 ☐ Temp. Stabilization     
☒ Perm. Stabilization     
☐ Other

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Monday, July 15, 2024

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, July 15, 2024

**Figure 1: STA 14310+00** – Controls in place and functioning properly.

☉ 330°NW (T) ● 17 N 605803 4100328 ±68ft ▲ 1148ft



Farmview

14310  
15 Jul 2024

**Figure 2: MVP-FR-313.01** – Controls in place and functioning properly.

☉ 348°N (T) ● 17 N 606525 4099706 ±13ft ▲ 1175ft



313.01  
15 Jul 2024

**Figure 3: MVP-FR-315** – Controls in place and functioning properly.

☉ 35°NE (T) ● 17 N 608324 4098897 ±36ft ▲ 1125ft



315  
15 Jul 2024

**Figure 4: STA 14411+00** – Controls in place and functioning properly.

☉ 90°E (T) ● 17 N 608364 4098997 ±13ft ▲ 1096ft



14411  
15 Jul 2024